

H&W Machine Repair & Rebuilding Inc.

2119 Meyer Road, Fort Wayne, IN 46803 Phone: (800) 285-5271 www.machinerypartsdepot.com

Servo Circuit Board Installation Notice

Before you disconnect you Servo Circuit Board you must mark each of the six connectors that plug into the board. If you reinstall the connectors into the wrong pins you stand a good chance of blowing the board and needing to be replace it. Remember, once the board is installed into the unit, you own it so if it blows because it was not reconnected correctly or you touched the back of the board to the side of the unit while under power you just threw the cost of the board into the trash. If you have any questions please contact us at 800-285-5271.



